


Risk 4

Getting hit by a moving object



Working safely together

Source measures

Provide the correct shielding.

Collective measures

Install temporary shielding.

Individual measures

For example, ensure that you are in the right place where you cannot be hit when working with wires and when performing hoisting operations.

PPE

Use the correct PPE.